

Latest HC06 AT firmware

I am trying to create an 8051 code library for HC06 bluetooth module. I have done one for my [my1barepi](#) library, so I thought that would be easy. Boy! Was I wrong! It turned out that the AT firmware on the latest HC06 module have been upgraded. The old ones do not need any CR/LF pair (the new ones do) and the AT command for changing name requires a ':' i.e. AT+NAME:<name> instead of just AT+NAME<name>. I am using AT firmware version 3.0-20170609 - not sure when this was changed. Maybe I need to update my my1barepi code? Since I no longer handle that paper, that is not in my priority list at the moment.

That is all I have to say about that.

From:

<https://azman.my1matrix.cc/> - **Azman @MY1**

Permanent link:

https://azman.my1matrix.cc/doku.php?id=blog:2022:0125_latest_hc06_at_firmware

Last update: **2026/02/25 23:37**

